

# LOC Ultra-Thin Round Panel Installation Guide

# SAFETY INSTRUCTIONS: Read instructions carefully before attempting to install fixture.

- Fixture must be wired in accordance with the National Electrical Code and all applicable local codes.
- This product must be installed in accordance with the applicable installations code by a person familiar with the construction and operation of the product and the hazards involved.

#### **CAUTION: Risk of fire**

- WARNING: Risk of electrical shock! Disconnect power before installing or servicing.
- WARNING: No user serviceable parts inside. To avoid electrical shock, do NOT disassemble the product.
- **WARNING:** Risk of fire or electric shock, installation requires knowledge of luminaires electrical systems. If not qualified, do **NOT** attempt installation. Contact a qualified electrician.
- WARNING: Do NOT make or alter any open holes in an enclosure of wiring or electrical components during kit installation.
- WARNING: To prevent wiring damage or abrasion, do NOT expose wiring to edges of sheet metal or other sharp objects.

#### **CLEANING & MAINTENANCE:**


CAUTION: Be sure the fixture temperature is cool enough to touch. Do NOT clean or maintain while the fixture is energized.

- 1. Clean frosted polystyrene lens and fixture with non-abrasive cleaning solution.
- 2. Do **NOT** open fixture to clean the LEDs. Do **NOT** touch the LEDs.

Note: These instructions do not cover all details or variation in equipment, nor do they provide for every possible situation during installation, operation or maintenance.

## **ADJUSTABLE CCT BUTTON:**

- Select the color temperature by adjusting the switch for desired CCT inside the junction box.
  - The CCT options are 2,700K / 3,000K / 3,500K / 4,000K / 5,000K
- Set your preferred color temperature before you install the light.





Phone: (844) LEDONE6 | Fax: 1-510-217-9461 | Web: www.ledonecorp.com



## **INSTALLATION:**

- 1. Turn power off.
- 2. Select preferred color temperature before installing the light.
- 3. Cut hole in the ceiling. Do NOT cut the hole larger than the frame plate opening. (Fig. 1)
- 4. Secure the junction box inside the ceiling. Connect the supply wires to the junction box. (Fig .2)
- 5. Insert round panel cord into the junction box and twist to lock. Push and hold both installation clips in a vertical position before inserting into the ceiling. (Fig. 3)





Phone: (844) LEDONE6 | Fax: 1-510-217-9461 | Web: www.ledonecorp.com